## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re: Patent Application of

Wen-Jen Tseng et al.

Patent No.: 6,459,413 : Issued: October 1, 2002

Appln. No.: 09/758,598 : Filing Date: January 10, 2001

For: MULTI-FREQUENCY BAND ANTENNA: Attorney Docket No. 681954-375

## REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT FOR USPTO MISTAKE (37 C.F.R. § 1.322)

Attached is PTO/SB/44 (also Form PTO-1050) in connection with the above issued patent.

The issued patent contains typographical errors which are the result of Patent and Trademark Office (USPTO) error. The errors to the issued patent appear correctly in the specification as filed as follow:

page 2, line 5: "operating(," should read -- operating --;
page 3, line 10: "provide(1" should read -- provided --;
page 8, line 15: "sinusuid" should read -- sinusoid --; and
page 11, line 2 of claim 1: "clement" should read -- element --.

It is submitted that the USPTO is responsible for the above-identified errors.

Accordingly, no fee should be charged to the patentee or their assignee for the correction.

It is believed that no fees are due. However, if any fees are due, please charge them to Deposit Account 50-1017.

In view of the above, it is believed that a Certificate of Correction is appropriate and is respectfully solicited.

Respectfully submitted,

By:

March 30, 2009

CLARK A. JABLON

Registration No. 35,039 PANITCH SCHWARZE BELISARIO & NADEL LLP

One Commerce Square

One Commerce Square

2005 Market Street, Suite 2200 Philadelphia, PA 19103-7013 Telephone: 215.965.1330

Direct Dial: 215.965.1293 Facsimile: 215.965.1331

E-Mail: cjablon@panitchlaw.com

CAJ/DCM Enclosures

Page \_\_1\_ of \_\_1\_

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number (Also Form PTO-1050)

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,459,413 B1	Page1 of1
APPLICATION NO.: 09/758,598	
ISSUE DATE : October 1, 2002	
INVENTOR(S) : Wen-Jen Tseng and Jyh-Wen Sheen	
It is certified that an error appears or errors appear in the above-identified pate is hereby corrected as shown below:	ent and that said Letters Patent
Column 1, line 37: "operating(," should read operating;	
Column 3, line 9: "provide(1" should read provided;	
Column 4, line 50: "sinusuid" should read sinusoid;	
Column 5, line 43: "clement" should read element	

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Clark A. Jabion, Esquire Panitch Schwarze Belisario & Nadel LLP 2005 Market Street, Suite 2200 Philadelphia, PA 18103

This collection of information is required by 37 CFR 1,322, 1,323, and 1,324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to (and by the LSH I/D to process) an appriament. Confidentiality is governed by 35 U.S. C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including plageneding, preparing, and submitting the completed application from the USEPTO. Time will vary depending upon the individual case. Any countries of the smooth of the smoot FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.